



R1

RTD Assembled thermistor thermometer sensor (fixed thread type)



Ordering Guide

R1 **PT1** - **A** - **2** - **KN** - **1/4** - **5** - **100** - **316**

Resistance	Accuracy	Number. of Element	Junction box
PT1.PT100	$A \pm (0.15 + 0.002 t)$	1.Single(default)	KN
PT2.PT500	$B \pm (0.3 + 0.005 t)$	2.Double,	KS
PT3.PT1000		Three group (optional)	KD

Screw thread	Protection tube OD	Protection tube length	Protection tube material
1/4 ; 1/2 ; 3/8 ; 3/4 ; 1	3.2 Ø 6.3 Ø 3.8 Ø 8 Ø 5 Ø 9.5 Ø	L (mm)	SUS304(default) SUS316L 310S(optional)

Dimension

